

FIGURE 1




FIGURE 2

Serial Port Settings

Serial Port:

Port type:

Baud rate:

Data bits:

Parity:

Stop bits:

Flow control:

COM 1

COM 2

RS-232

RS-485

9600

19200

38400

57600

115200

8

7

6

5

None

Even

Odd

1

2

None

RTS/CTS

DTR/DSR

Submit

Cancel

FIGURE 3

Flex / IO Port Settings

Port	Mode	Pull-up	Threshold*	Lower* (0-25.3V)	Upper* (0-25.3V)	Status
1	Digital Input	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	0.9	1.0	Off
2	Digital Output	<input checked="" type="checkbox"/>	<input type="checkbox"/>			Off (5V)
3	Digital Output	<input checked="" type="checkbox"/>	<input type="checkbox"/>			Off (5V)
4	Digital Output	<input checked="" type="checkbox"/>	<input type="checkbox"/>			Off (5V)

Submit Cancel

* Lower and Upper Threshold settings are for Digital Input only.

FIGURE 4




FIGURE 5




FIGURE 6




FIGURE 7




FIGURE 8




FIGURE 9




FIGURE 10

FIGURE 11A




FIGURE 11B





FIGURE 12






FIGURE 13